		GLASSIFIGATUM:			: 25X1
•	,"	CENTRAL INTELLIGEN Approved For Release 2003/08/06	ICE AGENCY · CIA-RDP80-008104	REPORT NO 000900780001-6	
		INFORMATION	REPORT	CD NO.	25X1A
C	TAUC	RY East Germany		DATE DISTR. 20 1	fay 1953
4.1	JBJE	CT Miscellaneous Railroad Information	4	NO. OF PAGES 2	
	-	25X1C	7		
			,	NO OF ENCLS.	25X1A
				SUPPLEMENT TO REPORT NO.	,
			25X1X		in companies and the fact of
25X <u>1</u>	7-7				
	1.	the intended control of in	ccur before 1 Apr	ril. because the e	boundary stablishment
25X1	2.	On 10 February, learned that the	Bahnbevollmaecht	tigte (anthorized	railroad export
/[		assigned to military transportation corregional railroad headquarters would sh	trol headquarters	s) (BBV) at the Gr	eifsweld
25X1	3.	On 13 February, learned that Vol	kspolizei RTOs wo	ould be establishe	d at Ebers-
		walde, Angermuande, Neustrelitz, Pasewa	lk, Stralsund and	l Bergen。2	25X1
25X1X	40				25X1
	Γ				<del></del> -
25X1X					
25 <mark>X1</mark>	<b>]</b> *•	railroad railroad system had been sent railroad repair shop for repair. In the overhead line operations. The benches c engines and brakes were defective and t	from the U.S.S.R. U.S.S.R. the car consisted of unpla the cables were pi	s had been conver- med pine boards. .eced together in	ide ted for All the a
		makeshift way. Normally, equipment in s However, the cars will be repaired for	uch poor condition further use.4	on would have been	deactivated.
25X1	6.		a special departm x Locomotive Fact	nent for the manuf cory at Babalsberg to be increased by	(formerly
	7。	On 14 February, Hetz (fmu), Director Ge preparations be made to evacuate the De specialized in the repair of motor rail installation was to be taken over by th railroad maintenance shops. Workers and who had previously worked at the Junker	ssau railroad rep coaches and engi e Wittenberge rai employees of the	air shop, which h nes. The work don lroad repair shop Dessau railroad	ad e by the and various repair shop,
			25X1	· ·	
1 1	STATE	CLASSIFICATION SECRET			25X1A
	ARMY		JITOIR		25X1A
					<b>¾</b>
	•	Approved For Release 2003/08/06	: CIA-RDP80-00810A	000900780001-6	3

25X1	SECRET, 2	25X1A
	<b>~ 2</b> ∞	
25X1A 25X1A	1. Comment. Information on the establishment of railroad check points along the sonal boundary in Berlin was transmitted previously. For last report, . The tightening of controls was originally to go into effect on 1 March 1953. It is believed credible that the delay reported was caused by a shortage of construction materials.	
25X1A 25X1A	2. Information on the establishment of VP transportation control headquarters in the Greifswald railroad district was transmitted previously.	
25X1A 25X1A	3. Comment. The shortage of transit-worthy freight cars was known previously. This situation forced the Fast German railroad administration to borrow equipment from Poland.	O
25X1A	Comment. These cars of the Berlin interurban railroad system were returned from the U.S.S.R. in 1952.	
25X1A	5. Comment: Lekemotivban Karl Marx Babelsberg, Abornstrasse 28-32.	
25X1A	6. Comment. This information is received for the first time and requires confirmation.	
	2	25X1A